

Table 1

**Beacon Environmental Services, Inc.
323 Williams Street
Bel Air, MD 21014 USA**

Analysis by EPA Method 8260C (Modified)

Client Sample ID:	mb121120a	Trip-1	A1	A2	A3	A4
Project Number:		2594	2594	2594	2594	2594
Lab File ID:	A12112003	A12112005	A12112006	A12112007	A12112008	A12112009
Received Date:		11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012
Analysis Date:	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012
Analysis Time:	14:25	15:10	15:33	15:55	16:18	16:40
Matrix:			Soil Gas	Soil Gas	Soil Gas	Soil Gas
Units:	ng	ng	ng	ng	ng	ng
COMPOUNDS						
Vinyl Chloride	<10	<10	<10	<10	<10	<10
cis-1,2-Dichloroethene	<10	<10	<10	<10	<10	<10
Trichloroethene	<10	<10	<10	<10	<10	<10

Table 1

Beacon Environmental Services, Inc.
323 Williams Street
Bel Air, MD 21014 USA

Analysis by EPA Method 8260C (Modified)

Client Sample ID:	A5	A6	A7	A8	B1	B2
Project Number:	2594	2594	2594	2594	2594	2594
Lab File ID:	A12112010	A12112011	A12112012	A12112013	A12112014	A12112015
Received Date:	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012
Analysis Date:	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012
Analysis Time:	17:03	17:26	17:48	18:10	18:33	18:56
Matrix:	Soil Gas	Soil Gas	Soil Gas	Soil Gas	Soil Gas	Soil Gas
Units:	ng	ng	ng	ng	ng	ng
COMPOUNDS						
Vinyl Chloride	<10	<10	<10	<10	<10	<10
cis-1,2-Dichloroethene	<10	<10	<10	<10	11	<10
Trichloroethene	<10	<10	<10	11	470	<10

Table 1

**Beacon Environmental Services, Inc.
323 Williams Street
Bel Air, MD 21014 USA**

Analysis by EPA Method 8260C (Modified)

Client Sample ID:	B3	B4	B5	B6	B7	B8
Project Number:	2594	2594	2594	2594	2594	2594
Lab File ID:	A12112016	A12112017	A12112018	A12112019	A12112020	A12112021
Received Date:	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012
Analysis Date:	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012
Analysis Time:	19:19	19:42	20:05	20:28	20:51	21:14
Matrix:	Soil Gas	Soil Gas	Soil Gas	Soil Gas	Soil Gas	Soil Gas
Units:	ng	ng	ng	ng	ng	ng
COMPOUNDS						
Vinyl Chloride	<10	<10	<10	<10	<10	<10
cis-1,2-Dichloroethene	<10	<10	<10	<10	<10	<10
Trichloroethene	<10	<10	<10	<10	<10	<10

Table 1

**Beacon Environmental Services, Inc.
323 Williams Street
Bel Air, MD 21014 USA**

Analysis by EPA Method 8260C (Modified)

Client Sample ID:	C1	C2	C3	C4	C4.5	C5
Project Number:	2594	2594	2594	2594	2594	2594
Lab File ID:	A12112022	A12112023	A12112024	A12112025	A12112026	A12112027
Received Date:	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012
Analysis Date:	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012
Analysis Time:	21:36	21:59	22:21	22:44	23:06	23:29
Matrix:	Soil Gas	Soil Gas	Soil Gas	Soil Gas	Soil Gas	Soil Gas
Units:	ng	ng	ng	ng	ng	ng
COMPOUNDS						
Vinyl Chloride	<10	<10	<10	<10	<10	<10
cis-1,2-Dichloroethene	<10	<10	<10	<10	<10	<10
Trichloroethene	<10	<10	<10	<10	<10	<10

Table 1

Beacon Environmental Services, Inc.
323 Williams Street
Bel Air, MD 21014 USA

Analysis by EPA Method 8260C (Modified)

Client Sample ID:	C5.5	C6	C6.5	C7	C8	CD6.5
Project Number:	2594	2594	2594	2594	2594	2594
Lab File ID:	A12112028	A12112029	A12112030	A12112031	A12112032	A12112033
Received Date:	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012
Analysis Date:	11/20/2012	11/21/2012	11/21/2012	11/21/2012	11/21/2012	11/21/2012
Analysis Time:	23:52	0:14	0:36	0:59	1:22	1:45
Matrix:	Soil Gas	Soil Gas	Soil Gas	Soil Gas	Soil Gas	Soil Gas
Units:	ng	ng	ng	ng	ng	ng
COMPOUNDS						
Vinyl Chloride	<10	<10	<10	<10	<10	<10
cis-1,2-Dichloroethene	<10	<10	<10	<10	<10	<10
Trichloroethene	<10	<10	<10	<10	<10	<10

Table 1

Beacon Environmental Services, Inc.
323 Williams Street
Bel Air, MD 21014 USA

Analysis by EPA Method 8260C (Modified)

Client Sample ID:	D1	D2	D3.5	D4	D4 DUP	D4.5
Project Number:	2594	2594	2594	2594	2594	2594
Lab File ID:	A12112034	A12112035	A12112036	A12112037	A12112038	A12112039
Received Date:	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012
Analysis Date:	11/21/2012	11/21/2012	11/21/2012	11/21/2012	11/21/2012	11/21/2012
Analysis Time:	2:07	2:30	2:53	3:15	3:38	4:01
Matrix:	Soil Gas	Soil Gas	Soil Gas	Soil Gas	Soil Gas	Soil Gas
Units:	ng	ng	ng	ng	ng	ng
COMPOUNDS						
Vinyl Chloride	<10	<10	<10	<10	<10	<10
cis-1,2-Dichloroethene	<10	<10	<10	<10	<10	<10
Trichloroethene	<10	<10	8 J	<10	<10	<10

Table 1

Beacon Environmental Services, Inc.
323 Williams Street
Bel Air, MD 21014 USA

Analysis by EPA Method 8260C (Modified)

Client Sample ID:	D5.5	D6	D6 DUP	D6.5	D7	D8
Project Number:	2594	2594	2594	2594	2594	2594
Lab File ID:	A12112040	A12112041	A12112042	A12112043	A12112044	A12112045
Received Date:	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012
Analysis Date:	11/21/2012	11/21/2012	11/21/2012	11/21/2012	11/21/2012	11/21/2012
Analysis Time:	4:23	4:46	5:08	5:30	5:53	6:16
Matrix:	Soil Gas	Soil Gas	Soil Gas	Soil Gas	Soil Gas	Soil Gas
Units:	ng	ng	ng	ng	ng	ng
COMPOUNDS						
Vinyl Chloride	<10	<10	<10	<10	<10	<10
cis-1,2-Dichloroethene	<10	<10	<10	<10	<10	<10
Trichloroethene	<10	<10	<10	<10	<10	<10

Table 1

Beacon Environmental Services, Inc.
323 Williams Street
Bel Air, MD 21014 USA

Analysis by EPA Method 8260C (Modified)

Client Sample ID:	DE3	DE3.5	DE3.5 DUP	DE4	DE4.5	DE4.5 DUP
Project Number:	2594	2594	2594	2594	2594	2594
Lab File ID:	A12112046	A12112047	A12112048	A12112049	A12112050	A12112051
Received Date:	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012
Analysis Date:	11/21/2012	11/21/2012	11/21/2012	11/21/2012	11/21/2012	11/21/2012
Analysis Time:	6:39	7:02	7:24	7:47	8:09	8:31
Matrix:	Soil Gas	Soil Gas	Soil Gas	Soil Gas	Soil Gas	Soil Gas
Units:	ng	ng	ng	ng	ng	ng
COMPOUNDS						
Vinyl Chloride	<10	<10	<10	<10	<10	<10
cis-1,2-Dichloroethene	<10	<10	<10	<10	<10	<10
Trichloroethene	19	43	53	73	<10	<10

Table 1

Beacon Environmental Services, Inc.
323 Williams Street
Bel Air, MD 21014 USA

Analysis by EPA Method 8260C (Modified)

Client Sample ID:	DE5	DE5.5	DE6	E1	E2	E3
Project Number:	2594	2594	2594	2594	2594	2594
Lab File ID:	A12112052	A12112053	A12112054	A12112055	A12112056	A12112057
Received Date:	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012
Analysis Date:	11/21/2012	11/21/2012	11/21/2012	11/21/2012	11/21/2012	11/21/2012
Analysis Time:	8:54	9:16	9:38	10:01	10:23	10:46
Matrix:	Soil Gas	Soil Gas	Soil Gas	Soil Gas	Soil Gas	Soil Gas
Units:	ng	ng	ng	ng	ng	ng
COMPOUNDS						
Vinyl Chloride	<10	<10	<10	<10	<10	<10
cis-1,2-Dichloroethene	<10	<10	<10	<10	<10	<10
Trichloroethene	<10	<10	<10	<10	<10	33

Table 1

Beacon Environmental Services, Inc.
323 Williams Street
Bel Air, MD 21014 USA

Analysis by EPA Method 8260C (Modified)

Client Sample ID:	E3.5	E4	E5	E6	E7	mb121121a
Project Number:	2594	2594	2594	2594	2594	
Lab File ID:	A12112058	A12112059	A12112060	A12112061	A12112062	A12112103
Received Date:	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012	
Analysis Date:	11/21/2012	11/21/2012	11/21/2012	11/21/2012	11/21/2012	11/21/2012
Analysis Time:	11:08	11:31	11:53	12:15	12:38	14:10
Matrix:	Soil Gas	Soil Gas	Soil Gas	Soil Gas	Soil Gas	
Units:	ng	ng	ng	ng	ng	ng
COMPOUNDS						
Vinyl Chloride	<10	<10	<10	<10	<10	<10
cis-1,2-Dichloroethene	686	19	<10	<10	<10	<10
Trichloroethene	16,265	683	<10	<10	<10	<10

Table 1

Beacon Environmental Services, Inc.
323 Williams Street
Bel Air, MD 21014 USA

Analysis by EPA Method 8260C (Modified)

Client Sample ID:	E8	F1	F2	F3	F4	F4 DUP
Project Number:	2594	2594	2594	2594	2594	2594
Lab File ID:	A12112105	A12112106	A12112107	A12112108	A12112109	A12112110
Received Date:	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012
Analysis Date:	11/21/2012	11/21/2012	11/21/2012	11/21/2012	11/21/2012	11/21/2012
Analysis Time:	14:55	15:17	15:40	16:03	16:25	16:48
Matrix:	Soil Gas	Soil Gas	Soil Gas	Soil Gas	Soil Gas	Soil Gas
Units:	ng	ng	ng	ng	ng	ng
COMPOUNDS						
Vinyl Chloride	<10	<10	<10	<10	<10	<10
cis-1,2-Dichloroethene	<10	<10	<10	<10	<10	<10
Trichloroethene	<10	<10	<10	67	<10	<10

Table 1

**Beacon Environmental Services, Inc.
323 Williams Street
Bel Air, MD 21014 USA**

Analysis by EPA Method 8260C (Modified)

Client Sample ID:	F5	F5 DUP	F6	F7	F8	G1
Project Number:	2594	2594	2594	2594	2594	2594
Lab File ID:	A12112111	A12112112	A12112113	A12112114	A12112115	A12112116
Received Date:	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012
Analysis Date:	11/21/2012	11/21/2012	11/21/2012	11/21/2012	11/21/2012	11/21/2012
Analysis Time:	17:11	17:33	17:56	18:18	18:41	19:03
Matrix:	Soil Gas	Soil Gas	Soil Gas	Soil Gas	Soil Gas	Soil Gas
Units:	ng	ng	ng	ng	ng	ng
COMPOUNDS						
Vinyl Chloride	<10	<10	<10	<10	<10	<10
cis-1,2-Dichloroethene	<10	<10	<10	<10	<10	<10
Trichloroethene	<10	<10	<10	<10	<10	<10

Table 1

Beacon Environmental Services, Inc.
323 Williams Street
Bel Air, MD 21014 USA

Analysis by EPA Method 8260C (Modified)

Client Sample ID:	G2	G3	G4	G4 DUP	G5	G6
Project Number:	2594	2594	2594	2594	2594	2594
Lab File ID:	A12112117	A12112118	A12112119	A12112120	A12112121	A12112122
Received Date:	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012	11/20/2012
Analysis Date:	11/21/2012	11/21/2012	11/21/2012	11/21/2012	11/21/2012	11/21/2012
Analysis Time:	19:26	19:49	20:11	20:34	20:56	21:19
Matrix:	Soil Gas	Soil Gas	Soil Gas	Soil Gas	Soil Gas	Soil Gas
Units:	ng	ng	ng	ng	ng	ng
COMPOUNDS						
Vinyl Chloride	<10	<10	<10	<10	<10	<10
cis-1,2-Dichloroethene	<10	<10	<10	<10	<10	<10
Trichloroethene	<10	<10	<10	<10	<10	<10

Table 1

Beacon Environmental Services, Inc.
323 Williams Street
Bel Air, MD 21014 USA

Analysis by EPA Method 8260C (Modified)

Client Sample ID: G7
Project Number: 2594
Lab File ID: A12112123
Received Date: 11/20/2012
Analysis Date: 11/21/2012
Analysis Time: 21:42
Matrix: Soil Gas
Units: ng

COMPOUNDS

Vinyl Chloride	<10
cis-1,2-Dichloroethene	<10
Trichloroethene	<10